EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	1355	steiger.in.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/02/22 14:16
S2	12	S1 near eckard	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/02/22 17:14
S3	6	(("4464653") or ("6032109") or ("5844411")).PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2007/02/22 17:15
S4	4060	((701/34,45) or (180/268,271)).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2007/02/22 17:28
S5	514	S4 and control$4 and processor and sensor	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/07/16 18:51
S6	560	S4 and control$4 and processor	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/02/22 17:41
S7	60	S5 and (sensor near3 (fault or faulty or abnormal or defect))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/02/22 18:00
S8	20	S5 and (sensor near2 housing)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/02/22 18:01
S9	4	S7 S8	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	AND	ON	2007/02/22 18:01

S10	36	("3863109" | "4223255" | "4338552" | "4648366" | "4786868" | "4803629" | "4937750" | "4966041" | "4996657" | "5011302" | "5029466" | "5065325" | "5119302" | "5130933" | "5157966" | "5164903" | "5215160" | "5218298" | "5247245" | "5275252" | "5275253" | "5303794" | "5357141" | "5371487" | "5418453" | "5707117" | "5754963" | "5809437" | "5819188" | "5828969" | "5838261" | "6314350" | "6326758" | "6439202" | "6456928" | "6481210").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2007/07/16 18:45
S11	25	("2005/0252709" | "5844411" | "6115654" | "6721639" | "6741919").URPN.	USPAT	OR	ON	2007/07/16 18:46
S12	1012	(automobile or car or vehicle) and control$4 and processor and (sensor near3 (fault or faulty or abnormal or anomaly or defect))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/07/16 18:56
S13	321	S12 and ("701"/$.ccls. or "180"/$.ccls. or "280"/$.ccls.)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/07/16 19:07
S14	148	(("5696777") or ("4317045") or ("4410803") or ("5184304") or ("5297052") or ("5433182") or ("5517911") or ("5590012") or ("5632246") or ("5671714") or ("5760421") or ("5913247") or ("6006598") or ("6111489") or ("4267505") or	USPAT	OR	OFF	2008/03/07 18:10

("4289955") or
("4291383") or
("4305785") or
("4319787") or
("4329730") or
("4359715") or
("4395630") or
("4408155") or
("4411577") or
("4455549") or
("4470496") or
("4472806") or
("4477976") or
("4482058") or
("4494208") or
("4494207") or
("4499584") or
("4499543") or
("4503963") or
("4509364") or
("4521769") or
("4534214") or
("4538199") or
("4539520") or
("4547658") or
("4587615") or
("4761704") or
("4771181") or
("4786868") or
("4830137") or
("4845435") or
("4862298") or
("4914385") or
("4916612") or
("4937732") or
("4939435") or
("4974572") or
("5017910") or
("5185590") or
("5189914") or
("5214373") or
("5343155") or
("5349654") or
("5363303") or
("5366110") or
("5369392") or
("5370449") or
("5371487") or
("5384707") or
("5406472") or
("5422545") or
("5424898") or
("5436826") or
("5469825") or
("5481906") or

("5517175") or
("5521782") or
("5526916") or
("5529298") or
("5563489") or
("5579235") or
("5585778") or
("5600498") or
("5602757") or
("5617280") or
("5621598") or
("5650902") or
("5703575") or
("5754113") or
("5765664") or
("5768614") or
("5801940") or
("5815357") or
("5832356") or
("5864055") or
("5896257") or
("5902099") or
("5921373") or
("5956663") or
("5963706") or
("5965825") or
("5969919") or
("5983859") or
("6000040") or
("6016993") or
("6016994") or
("6019310") or
("6024324") or
("6029930") or
("6032648") or
("6036633") or
("6039254") or
("6104304") or
("6125985") or
("6129425") or
("6144903") or
("6142283") or
("6152702") or
("6153948") or
("6161058") or
("6163144") or
("6168197") or
("6182507") or
("6194849") or
("6202412") or
("6205009") or
("6211631") or
("6211631") or
("6242993") or
("6289267") or

		("6292717") or ("6464798") or ("20080015794") or ("4379520") or ("4538095") or ("4791394") or ("RE32901") or ("5747950") or ("4429998") or ("4530024") or ("4626832") or ("4870269") or ("4896089") or ("5222065") or ("5416418") or ("5517102") or ("5543708") or ("5752208") or ("6012005") or ("6053031") or ("6112150") or ("6122577") or ("6178947") or ("6189981") or ("4347432")).PN.				
S15	1	(("5696777") or ("4317045") or ("4410803") or ("5184304") or ("5297052") or ("5433182") or ("5517911") or ("5590012") or ("5632246") or ("5671714") or ("5760421") or ("5913247") or ("6006598") or ("6111489") or ("4267505") or ("4289955") or ("4291383") or ("4305785") or ("4319787") or ("4329730") or ("4359715") or ("4395630") or ("4408155") or ("4411577") or ("4455549") or ("4470496") or ("4472806") or ("4477976") or ("4482058") or	US-PGPUB	OR	OFF	2008/03/07 18:11

("4494208") or
("4494207") or
("4499584") or
("4499543") or
("4503963") or
("4509364") or
("4521769") or
("4534214") or
("4538199") or
("4539520") or
("4547658") or
("4587615") or
("4761704") or
("4771181") or
("4786868") or
("4830137") or
("4845435") or
("4862298") or
("4914385") or
("4916612") or
("4937732") or
("4939435") or
("4974572") or
("5017910") or
("5185590") or
("5189914") or
("5214373") or
("5343155") or
("5349654") or
("5363303") or
("5366110") or
("5369392") or
("5370449") or
("5371487") or
("5384707") or
("5406472") or
("5422545") or
("5424898") or
("5436826") or
("5469825") or
("5481906") or
("5517175") or
("5521782") or
("5526916") or
("5529298") or
("5563489") or
("5579235") or
("5585778") or
("5600498") or
("5602757") or
("5617280") or
("5621598") or
("5650902") or
("5703575") or
("5754113") or

("5765664") or
("5768614") or
("5801940") or
("5815357") or
("5832356") or
("5864055") or
("5896257") or
("5902099") or
("5921373") or
("5956663") or
("5963706") or
("5965825") or
("5969919") or
("5983859") or
("6000040") or
("6016993") or
("6016994") or
("6019310") or
("6024324") or
("6029930") or
("6032648") or
("6036633") or
("6039254") or
("6104304") or
("6125985") or
("6129425") or
("6144903") or
("6142283") or
("6152702") or
("6153948") or
("6161058") or
("6163144") or
("6168197") or
("6182507") or
("6194849") or
("6202412") or
("6205009") or
("6211631") or
("6211631") or
("6242993") or
("6289267") or
("6292717") or
("6464798") or
("20080015794") or
("4379520") or
("4538095") or
("4791394") or
("RE32901") or
("5747950") or
("4429998") or
("4530024") or
("4626832") or
("4870269") or
("4896089") or
("5222065") or

		("5416418") or ("5517102") or ("5543708") or ("5752208") or ("6012005") or ("6053031") or ("6112150") or ("6122577") or ("6178947") or ("6189981") or ("4347432")).PN.				
S16	22	(sensor sensing) same (digital near2 interface) same (fault$2 error failure defect$3 anomaly) same bit	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/07 18:32
S17	1	S14 and ((sensor sensing) same (fault$2 error failure defect$3 anomaly) same bit)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/07 19:15
S18	121	S14 and ((sensor sensing) same (fault$2 error failure defect$3 anomaly))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/07 19:15
S19	24	S14 and (bit "MONI" "MISO")	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/07 19:17
S20	22	S18 and S19	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/07 19:17
S21	6293	(sensor sensing) same (fault$2 error failure defect$3 anomaly) same (bit "MONI" "MISO")	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/07 19:21
S22	94	S21 and ("digital interface")	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/07 19:22
S23	420	((sensor sensing) near2 (monitor$3 control$4)) same (fault$2 error failure defect$3 anomaly) same (bit "MONI" "MISO")	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/07 19:24
S24	5	S23 and ("digital interface")	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/07 19:24

S25	48	("3852730" | "3863109" | "3872389" | "3964018" | "4223255" | "4231249" | "4279151" | "4311895" | "4328494" | "4338552" | "4475823" | "4648366" | "4727359" | "4783659" | "4786868" | "4803629" | "4841286" | "4882564" | "4937750" | "4966041" | "4996657" | "5011302" | "5029466" | "5051743" | "5065325" | "5119302" | "5130933" | "5157966" | "5164903" | "5215160" | "5218298" | "5235527" | "5247245" | "5275252" | "5275253" | "5294890" | "5303794" | "5319576" | "5350237" | "5357141" | "5371487" | "5418453" | "5707117" | "5754963" | "5809437" | "5819188" | "5828969" | "5838261").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2008/03/08 15:43
S26	88	("2005/0252709" | "4464653" | "5703575" | "5844411" | "6115654" | "6721639"). URPN.	USPAT	OR	ON	2008/03/08 15:43
S27	3	("4422073").PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2008/03/14 17:48
S28	1984	(("rotation rate" rotation) near2 sensor) same (fault$2 error failure defect$3 anomaly)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/14 20:45
S29	8	S28 and "restraint system"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2008/03/14 20:46

| S30 | 82 | (automobile or car or vehicle) same (("rotation rate sensor" "rotation sensor") with (fault$2 error failure defect$3 anomaly)) | US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT | OR | ON | 2008/03/14 20:49 |

3/15/2008 5:41:40 PM
C:\Documents and Settings\cpnguyen\My Documents\EAST\Workspaces\Application_10521694_NF2.wsp